Point Type		DPA_GROUP			
PtType	RepairStatus	FEDERAL	LOCAL	STATE	<b>Grand Total</b>
Chipping Slash	Identified for Repair	22	6	21	49
<b>Chipping Slash Total</b>		22	6	21	49
Culvert Damage	Identified for Repair	7		2	9
<b>Culvert Damage Total</b>		7		2	9
Dozer Push	Completed	1		2	3
	Identified for Repair	3			3
<b>Dozer Push Total</b>		4		2	6
Drop Point	Completed			1	1
	Identified for Repair	16	9	7	32
<b>Drop Point Total</b>		16	9	8	33
Fence Damage	Completed	1		1	2
	Identified for Repair	84	12	24	
Fence Damage Total		85	12	25	122
Gate Damage	Identified for Repair	1			1
Gate Damage Total		1			1
Hazard Tree	Identified for Repair		2		2
Hazard Tree Total	Ldes-CC 14 D		2		2
HazMat Site	Identified for Repair	3			3
HazMat Site Total	Identificat for D	3			3
Helispot	Identified for Repair	6			6
Helispot Total	Identified for Denoir	6		2	<b>6</b>
Lop & Scatter Trees Lop & Scatter Trees To	-	1		2	3
Noxious Weeds	Identified for Repair	4		Z	3
Noxious Weeds Total	identified for Repair	4			4
OIL	Identified for Repair	<u>_</u>		6	6
OIL Total	raerianea rei reepan			6	6
Other	Identified for Repair	3		5	8
Other Total	•	3		5	8
Other Sensitive Res	Identified for Repair	9			9
Other Sensitive Resource Total		9			9
Road Repair Needed	•	1		3	4
	Identified for Repair	13	1	4	18
Road Repair Needed T	_	14	1	7	22
Road Sign Damage	-	2			2
Road Sign Damage To		2			2
Safety Zone	Identified for Repair	4			4
Safety Zone Total	lala a titi a al ta a Danaia	4			4
Sensitive Plant Spec Identified for Repair Sensitive Plant Species Total		1			1
Staging Area	Identified for Repair	1	1	2	1
Staging Area Total	identified for Repair	1	1	2	4
Stream Crossing	Identified for Repair	3	•	6	9
Stream Crossing Total	•	3		6	9
Structure Wrap	Identified for Repair	1			1
Structure Wrap Total		1			1
Trail Damage	Identified for Repair	1	1		2
Trail Damage Total		1	1		2
Water Bar	Completed	1		2	3
	Identified for Repair	10			10
	In Progress	1			1
Water Bar Total		12		2	14
Water Development	-	9			9
Water Development Damage Total Wilderness Incursion Identified for Repair		9			9
	•	2			2
Wilderness Incursion		Z			2
WS WS Total	Identified for Repair	4 4			4
			22	88	335
Grand Total		215	32	88	335